

March 2024

85 Minamiyamada-cho, Kusatsu City,
Shiga Prefecture, Japan

Canon Machinery Inc.
FA Solution Division

Important Notice : Discontinued Parts for Maintenance Service

Dear Customer,

We would like to take this opportunity to thank you for your continued support.
We inform you of the discontinuation of our maintenance service.

We have been responding to inquiries from our customers regarding the following equipment, but we have received notification from the manufacturer of the final discontinuation of maintenance service for the parts in the attached list.

In this connection, I would appreciate it if you could place a final order for the parts and related inspection/repair/overhaul.

Applicable devices BESTEM-D01, D01R, D01Np, D02, D03, D03Hp, CPS-6800N

Please refer to the attached table for the applicable parts.

Final order receipt date: May 31, 2024

We will continue to communicate with our customers regarding this matter.

Sincerely yours

【List of end-of-support items】 BESTEM-D01/D01R/D01Rp/D02/D03/D03Hp/CPS-6800N

Maker	Item Name	Model number	Remark	Function	Information		
OMRON	Controller components	NC2BC-CB3NM-MXP-CPU1MMI Type	MMI CPU board		Last order of Parts/repair : End of May 2024		
		NC2BC-CB3NM-MXP-CPUCTR Type	Controller CPU board				
		NC2BC-CB3NM-MX03-D10	D10 board	Controls digital input/output signals			
		NC2BC-CB3NM-MXP-D1032-01	D10 board	Controls digital input/output signals			
		NC2BC-CB3NM-MXP-D164-01	D1 board	Controls digital input signals			
		NC2BC-CB3NM-MXP-D064-01	D0 board	Controls digital output signals			
		NC2BC-CB3NM-MAP-D1128-01	D1 board	Controls digital input signals			
		NC2BC-CB3NM-MAP-D0128-01	D0 board	Controls digital output signals			
		NC2BC-CB3NM-MAP-A103522-01	A10 board	Controls analog input and output			
		NC2BC-CB3NM-MX01-NC8	Motion board	Controls motor			
		NC2BC-CB4NM-MA04-NC8S	Motion board	Controls motor			
		NC2BC-CB3NM-MXP-NC508-01	Motion board	Controls motor			
		NC2BC-CB3NM-MAP-NC578-01	Motion board	Controls motor			
		NC2BC-CB3NM-MXP-NC534-01	Motion board	Controls motor			
		NC2BC-CB3NM-MXP-D0M4G-02	DOM				
		NC2BC-CB2NM-BXDOM4GCTRL-02	DOM				
		NC2BC-DM1NM-SPP-D0M4G-02	DOM				
		NC2BC-CB2NM-BXDOM4GMMI-02	DOM				
		NC2BC-CB3NM-MXP-IDC90-02	IDC Cable				
		NC2BC-CB4NM-MA04-NEW1G2	Memory				
		NC2BC-CB3NM-MXP-FANRACK-01	Fan rack				
		NC2BC-CB3NM-MXP-FAN12-01	Fan				
		NC2BC-CB3NM-MAP-FAN28-01	Fan				
		NC2BC-CB3NM-MXFILTER	Filter				
		NC2BC-CB3NM-MXP-PS350-01	Power supply				
		NC2BC-CB3NM-MXP-FAN775-01	Fan				
		IPC610BPF7009E-T / Chassis	Chassis				
		989K611520E / Backplane	Backplane				
		★NC2BC-CB3NM-MXP-A101711-02	A10 board	Controls analog input and output		★Not available: discontinued by manufacture	
		★NC2BC-CB4NM-MA04-NC8SN	Motion board	Controls motor			
		★NC2BC-CB3NM-MAP-NC578-02	Motion board	Controls motor			
		Sensor controller	FZ5 Series FH Series			Only provide repair service until end of March 2028 (Only BESTEM-D03Hp)	
		Yaskawa	Servo motor Σ II type	SGMAH Series			Only provide repair service until 20th March 2025
SGDM Type							
Servo pack Σ II type	SGDH Type						
	SGDD Type						
	SGDJ Type						
Servo motor Σ III type	SGMAS Type						
Mitsubishi	Servo pack Σ III type	SGDS Type					
		HC-MES Type					
	Servo driver JS2 series	MR-J2S Type					
		HF-MP Type					
Servo motor JS3 series	HF-KP Type						
	MR-J3 Type						
Linx	Recognition board	Ginga ++/M2		Last order of Parts/repair : End of May 2024			
		Ginga ++/M4					
		Ginga digital-CL2					